M. A. R. 57 (Rule 116)
Measurement Book

No. B 342025

....From..... To.....

...ture of Agency .....

...of work .....

...tion, etc, of work	Dimensions				Contents	Reference to last Measurement
	Number	Length	Breadth	Depth		
2	3	4	5	6	7	8
...ggregate wet mix macadam Specification, ...ing premixing the material with water at ...n mechanical mix plant carriage of mixed ...d of tipper to site, laying in uniform layers ...paver in site laying sub-base/base course on ...prepared surface & compacting with vibratory rolle... achieve the desired compaction complete as per specifica... Qty vide pg no. SA 2022/1 of this M.B.					529.29 cum 526.5	

Date	Full description, etc, of work	Dimensions				Contents	R Me
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	
I-1	Providing & applying primer coat from 7.5 to 9.8 kg & 9.8 to 12.2 kg / 10 sqm for surface of low & medium porosity respectively over prepared surface of granular base with cut back M.C-70 or any other bitumen mixed with diesel at 10 kg/per 10sqm including cost of all materials labour, machinery complete as per specifications.						
	Qty vide pg no 342823/2 of this M.B					26467 Sqm @ 80.78	
I-5	Providing & laying semidense bituminous concrete						

Date	Full description, etc, of work	Dimensions				Contents
		Number	Length	Breadth	Depth	
1	2	3	4	5	6	7



Asst. N.I.C. : 22/6/16.

2149152=

M. A. R. 57 (Rule 116)

Measurement Book

No. B 342028

Amount admitted for Rs. .....

By Cheque for Rs. 1869585=

From ..... To .....

Nature of Agency .....

Agreement of work 279567=

Description, etc, of work	Number	Dimensions: Length	Breadth	Depth	Contents	Reference to last Measurement
	3	4	5	6	7	8
Executive Engineer						
Unit: 2 Superintendent						
S.D.M.F. Nagarmahal						
Disposal of debris to the final place of disposal, all lead & lift & as direction by the engineer in charge of the work.						
As per vide						
Total Amount					396.97 cum @ 94.82 M	37641=00
						1953775=00
						195327=00
						2149152=00

KR/DL 10/ 195689=00 — 2152589=00

22/6/16

Certificate:-

Certified that contractor has done the work satisfactory & removed all the debris from work spot